



# **Manual Insert**

SEGA Service Department 45133 Industrial Drive Fremont, Ca. 94538 http://www.sgwservice.com Phone: 650.632.7580 Fax: 650.632.7594

### **UL MODIFICATIONS TO AIRLINE PILOT DX FOR US**

#### ASSY BILLBOARD (APC-4500)

1.) All ballast and light fixtures are UL listed and can be purchased locally at almost any hardware and/or lighting store.

2.) In the Marquee is an 18" 15W Fluorescent fixture. It requires an 18" 15W Fluorescent Lamp. Ballast is Rapid Start located behind marquee metal. Ballast is a Radionic R+4522tp.

3.) There is also a 25W 120V lamp on each side of the marquee, these are also UL listed and can be obtained at almost any local hardware store.

#### ASSY SLIM LAMP UNIT (APC-3150)

4.) The Fluorescent fixture in the Arm rest is also 15W and UL listed.

#### CONNECT BD (838-11856CE)

5.) The fuse located on the Connect BD is 6.25A instead of 6.34A CE

#### WOOFER AMP 50Wx2 (838-13723)

6.) The fuses used on the Woofer Amp are also 6.25A

If you have any problems locating these parts at your local hardware store please contact our service department at the numbers listed above and we will try to help you locate them.

### Warranty

Your new Sega Product is covered for a period of 90 days from the date of shipment. This certifies that the Printed Circuit Boards, Power Supplies and Monitor are to be free of defects in workmanship or materials under normal operating conditions. This also certifies that all Interactive Control Assemblies are to be free from defects in workmanship and materials under normal operating conditions. No other product in this machine is hereby covered.

Sellers sole liability in the event a warranted part described above fails shall be, at its option, to replace or repair the defective part during the warranty period. For Warranty claims, contact your Sega Distributor.

Should the Seller determine, by inspection that the product was caused by Accident, Misuse, Neglect, Alteration, Improper Repair, Installation or Testing, the warranty offered will be null and void.

Under no circumstances is the Seller responsible for any loss of profits, loss of use, or other damages.

This shall be the exclusive written Warranty of the original purchaser expressed in lieu of all other warranties expressed or implied. Under no circumstance shall it extend beyond the period of time listed above.

#### OPTIONAL DOLLAR BILL ACCEPTOR

THE COIN DOOR ASSEMBLY USED ON AIRLINE PILOT COMES EQUIPPED TO ACCEPT A DOLLAR BILL ACCEPTOR. ALL NEEDED WIRING CONNECTIONS ARE CONVIENENTLY LOCATED INSIDE THE GAME FOR THIS APPLICATION.	
THE COIN DOOR CAN ACCCOMMODATE THE FOLLOWING VALIDATORS:	
HOLE POSITION#1 (FORWARD-MOST POSITION)	Mars 2000 series
HOLE POSITION#2	Mars 2000 series DBV45 (JCM)
HOLE POSITION #3	CURRENTLY NOT USED
HOLE POSITION #4	DSI01*
*The back flange on the chute can be removed for hold position #4. If the flange is not removed, it may interfere with the back of the cabinent.	

The frame and cashbox enclosure on this coindoor has been modified to accomodate a Mars 2000 series upstacker. A 2000 series stacker can be added by simply removing the top two entry door and replacing it with a one entry door with a cut-out for a stacker. This one entry door can be ordered through Coin Controls or one of Coin Controls authorized distributors. The part number is 91-4000-01. The Mars stacker can be obtained through an autherized Mars distibutor.



JAN. 1998

## **VISIT OUR WEBSITE!**

