

SPECIAL NOTICE FOR NASCAR Deluxe Games

PROBLEM: Heat building up in the CPU area is causing the Game to Freeze.

SOLUTION: Open the rear CPU access panel at the Tail of the game. Remove the CPU/ Power Supply tray. Also, remove the exhaust fan mounted in the Right, outside wall. Cut a 4" diameter hole in the inter wood partition as shown below. Re-assemble components.

This will allow better Ventilation, and air flow from the CPU board by reducing the tempertaure in the CPU cage. If your game does not have a fan, please install a 4" 120V unit.



IMPORTANT!

Not following the directions provided herein may cause your game to malfunction. All electrical work should be performed by the site's Serviceman or Technician.

If you have any questions please contact the SEGA Service Department at the numbers given above.